


## CORNER RECORD

Document Number CR 5096

City of Oakland

County of Alameda, California

**Brief Legal Description** Pln & Disc monument on Fruitvale Ave @ School St.



### CORNER TYPE

Government Corner	<input type="checkbox"/>	Control	<input checked="" type="checkbox"/>
Meander	<input type="checkbox"/>	Property	<input type="checkbox"/>
Rancho	<input type="checkbox"/>	Other	<input checked="" type="checkbox"/>

Date of Survey 6/6/2012.

**COORDINATES (Optional)**

N.	<u>14NW2=476,394.03; 19/D = 476,352.83</u>			
E.	<u>14nw2=1,503,933.63; 19/D = 1,503,963.02</u>			
Zone	NAD27	<input checked="" type="checkbox"/>	NAD83	<input type="checkbox"/>
NAD83 Epoch				
Elev.				
Vert. Datum:	NGVD29	<input type="checkbox"/>	NAVD88	<input type="checkbox"/>
Meas. Units:	Metric	<input type="checkbox"/>	Imperial	<input type="checkbox"/>

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Pin Mon(14NW2) & Disc Mon(19/D/14) in standard castings and shown on monument index sheet # 189.

See pg 2 . Reference : Mon Tie Bk 22 Pg 28 City of Oakland

In compliance with section 8871 of the PLS Act, this corner record is being filed PRIOR to improvements in the intersection of Fruitvale Ave and School St.


A description of the physical condition of the monument as found and as set or reset:

The monuments were found in good condition.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on 12-17-13

Signed ~~\_\_\_\_\_~~ RLS or R.C.E. No. 4700



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received

and examined and filed

Signed

## Title

P.L.S or R.G.E. No. 5724

**County Surveyor's Comment:**

